PRIME Building Inspections Home Inspection Report



888 Main Street, Anytown NJ, 01234 Inspection prepared for: John and Jane Doe Inspection Date: 10/10/2011 Time: 1:30pm - 4:00pm Age: 24 years (Built 1987) Size: Approx 1,800 sf Weather: Sunny. Approx 82 degrees

> Inspection No. SCsample4 Date of Report: October 11, 2011

Inspector: Stanley E. Chow NJ Home Inspector License No. 24GI00110100 11303 Harcross Court, Princeton, NJ 08540-6582 Phone: 888.920.0500 Fax: 877.833.2007

Email: stan@PrimeBuildingInspections.com www.PrimeBuildingInspections.com



STANLEY E. CHOW, New Jersey Home Inspector License No. 24GI00110100. This Home Inspection Report ("Report") was prepared by me or under my direct supervision. I hereby attest the contents of this Report to be accurate at the time of inspection to the best of my knowledge and ability. All information contained within this Report is privileged and confidential material. This Report was prepared for the sole use and exclusive benefit of the Client(s) named herein and Client(s) is/are granted a non-transferable limited license to use this Report for their benefit only. PRIME Building Inspections retains full ownership of this Report in portions and in whole. This Report may not be copied in any form or distributed to third parties through any media without prior written permission from PRIME Building Inspections. No responsibility or liability is assumed for any unauthorized or illegal use. Copyright 2011-2012 PRIME Building Inspections. All Rights Reserved.

Executive Summary

The Executive Summary below represents the Inspector's professional opinion on potentially significant findings and observations where action is HIGHLY RECOMMENDED. These findings and observations may be safety hazards, deficiencies requiring significant expense for corrective work or items where extra attention is required by the Client. This summary is not intended to be a complete listing of all the findings and observations in the Report. Please review this Report in its entirety as the Executive Summary alone does not fully explain all the issues. All recommendations, whether referred to as RECOMMEND or HIGHLY RECOMMEND, contained in this report for further review, inspections, evaluations, tests, installations, repairs, replacements and other services must be performed by qualified licensed/certified contractors or experienced professional consultants. All work and services provided pursuant to recommendations contained in this Report must be performed in strict compliance with all applicable rules, regulations, codes, laws and manufacturer's recommendations and/or requirements.

Exterior of House a	Exterior of House and Adjacent Areas			
Page 10 Item: 1	Vegetation Affecting Structure	• HIGHLY RECOMMEND having all trees trimmed and pruned away from house.		
Page 11 Item: 7	Eaves, Soffits, Fascia and Trim	 Observed rotted wood in band trim on South side above stucco. HIGHLY RECOMMEND repair or replacement. 		
Roofing	1			
Page 15 Item: 3	Roof Covering	• Algae stains on roof shingles indicate a high moisture level in shingles. HIGHLY RECOMMEND engaging a qualified roofing contractor for further review and evaluation; and to repair and/or replace roof shingles as necessary.		
Page 17 Item: 7	Roof Drainage System	• Observed excessive amounts of leaves and debris in gutters. HIGHLY RECOMMEND removing leaves and debris to prevent clogs and to provide free flow drainage. Clogged gutters promote water intrusion and ice dams that can damage building components and support mold growth.		
Interior	1			
Page 22 Item: 9	Garage Fire Separation Wall and Ceiling	 Integrity of fire separation wall and ceiling in Garage is compromised by two openings. HIGHLY RECOMMEND repair with drywall to minimize fire risk for greater protection. 		
Heating and Air Cor	nditioning			
Page 31 Item: 6	Venting, Flue(s), and Chimney(s)	 Observed combined furnace/water heater vent pipe is too close to combustibles and does not meet current safety and fire prevention standards. HIGHLY RECOMMEND further review and evaluation by a qualified licensed HVAC contractor and to remediate deficiencies and defects to minimize fire risk. Observed transition connector pipe combining furnace and water heater vents are potentially undersized for safe exhaust of flue gases and efficient operation of appliances. HIGHLY RECOMMEND further review and evaluation by a qualified licensed HVAC contractor and to repair and remediate deficiencies and defects. 		
Plumbing				
Page 37 Item: 16	Pump(s)	 The sump pump did not operate when tested. HIGHLY RECOMMEND replacement by a qualified licensed plumbing contractor. 		
Electrical				

Stanley E. Chow

	• Observed 3 screws were missing at dead front cover where 6 screws are required. One of the 3 installed screws was pointed and wrong size. Blunt-tip screws are required at electric panels to prevent accidental piercing of wires and cables. HIGHLY RECOMMEND engaging a qualified licensed electrical contractor to install proper screws.
Page 40 Item: 9	• SAFETY CONCERN: Observed receptacle outlets in Bedroom #2 were painted. Ground pin slots were coated with paint and prevented plug insertions. HIGHLY RECOMMEND replacement of receptacle outlets by a qualified and licensed electrical contractor.

888 Main Street, Anytown, NJ

Preface

The subject home and adjacent surrounding property were inspected and this Home Inspection Report was prepared by PRIME Building Inspections to comply with the Standards of Practice set forth in New Jersey Administrative Code (N.J.A.C. 13:40-15.16). As such, we inspect the *readily accessible, visually observable, installed systems and components* of a home. This Report contains observations of those systems and components that, in the professional judgment of the Inspector, are not functioning properly, significantly deficient, unsafe, or are near the end of their service lives. If the cause for the deficiency is not readily apparent, the suspected cause or reason why the system or component is at or near end of expected service life is reported, and recommendations for correction or monitoring are made as appropriate.

A complete copy of the Standards of Practice of the State of New Jersey was provided to the client at or prior to the time of inspection, and is also available online at: www.state.nj.us/lps/ca/laws/hiacregs.pdf.

Inspectors are NOT required to determine: the condition of any system or component that is not readily accessible; the remaining service life of any system or component; the strength, adequacy, effectiveness or efficiency of any system or component; causes of any condition or deficiency; methods materials or cost of corrections; future conditions including but not limited to failure of systems and components; the suitability of the property for any specialized use; compliance with regulatory codes, regulations, laws or ordinances; the market value of the property or its marketability; the advisability of the purchase of the property; the presence of potentially hazardous plants or animals including but not limited to mold, mildew and other fungal growth, radon gas, termites and other wood destroying insects, the presence of any environmental hazards including, but not limited to toxins, carcinogens, noise, and contaminants in soil, water or air; the effectiveness of any system installed or methods utilized to control or remove suspected hazardous substances; the operating costs of any systems or components; and the acoustical properties of any systems or components

Inspectors are NOT required to inspect underground items including, but not limited to underground storage tanks or other underground indications of their presence, whether abandoned or active; systems or components that are not installed; decorative items; systems or components that are in areas not entered; detached structures other than carports or garages; common elements or common areas in multi-unit housing, such as condominium properties or cooperative housing.

Inspectors are NOT required to perform any procedure or operation which will, in the opinion of the Inspector, likely be dangerous to the Inspector or others or damage the property, its systems or components; move suspended ceiling tiles, personal property, furniture, equipment, plants, pets, soil, snow, ice or debris or dismantle any system or components.

Inspectors are NOT required to enter under-floor crawlspaces or attics that are not readily accessible nor any area which will, in the opinion of the Inspector, likely be dangerous to the inspector or others persons or damage the property or its systems or components.

Inspectors are NOT required to operate any system or component that is shut down or otherwise inoperable; any system or component which does not respond to normal operating controls or any shut-off valves.

Inspectors are NOT required to offer or perform any act or service contrary to law; offer or perform architectural services, engineering services or work in any trade or professional service other than home inspection.

No guarantee or warranty of the property, home, or any components are expressed or implied by this Report, the Inspector, or PRIME Building Inspections.

The contents and confidential use of this Report are governed by the terms and conditions of the Pre-Inspection Agreement executed between the Client and PRIME Building Inspections.

Conventions and Terms Used in this Report

USE OF PHOTOS:

Your report includes many photographs. Some pictures are informational and of a general view, to help you understand where the Inspector has been, what was looked at, and the condition of the item or area at the time of the inspection. Some of the pictures may be of problem areas, these are to help you better understand what is documented in this report and to help you see areas or items that you normally would not see. Not all problem areas or conditions will be supported with photos.

TEXT COLOR SIGNIFICANCE:

GREEN colored text: Denotes general/descriptive comments on the systems and components installed at the property. Limitations, if any, that restricted the inspection, associated with each area, are listed here as well.

BLUE colored text: Denotes observations and information regarding the condition of the systems and components of the home. These include comments of deficiencies that are less than significant; or comments which further expand on a significant deficiency; or comments of recommendations, routine maintenance, tips, and other relevant resource information.

RED colored text: Denotes a brief comment of significant deficient components or conditions that requires immediate attention attention, repair, or replacement. These comments are also duplicated in the Executive Summary section.

COMMONLY USED TERMS:

"SAFETY CONCERN": A condition, system or component that is considered harmful or dangerous due to its presence or absence.

"DEFERRED COST": Denotes a system or component that is near or has reached its normal service life expectancy or shows indications that it may require repair or replacement anytime within the next five (5) years.

"MAINTENANCE": Recommendations for the proper operation and routine maintenance of the home.

"IMPROVE": Denotes improvements which are recommended but not required. These may be item identified for upgrade to modern and safety standards.

"FMI": For More Information: Includes additional reference information and/or weblinks to sites which expand on installed systems and components and important consumer product information.

"FYI": For Your Information: Denotes a general information and/or explanation of conditions, safety information, cosmetic issues, and useful tips or suggestions for home ownership.

KEY TO RATINGS:

Inspect = INSPECTED: A system or component that was visually examined. It was observed to be in good functional condition as originally intended, engineered, or designed with normal wear and tear and with no major damage or apparent material defects.

Not

Inspect = NOT INSPECTED: A system or component that was not ON or was shut off at the time of inspection and could not be examined and evaluated using normal control devices; or a system or component that was hidden or obstructed from visual examination by items such as furniture, personal property, or other coverings preventing readily available and free access. Reason for non-inspection is provided within this report.

Not

Presnt = NOT PRESENT: A system or component that did not exist or was not visually evident on this property at the time of inspection.

Repair

Replac = REPAIR or REPLACE: A system or component that was not in good functional condition, unsafe or not operating as originally intended, engineered, or designed. Recommend engaging a qualified licensed/certified contractor or experienced professional consultant for further review, inspection, or evaluation; and to perform any necessary repairs, replacements, installations or tests as necessary to bring the system or component into good functional condition and safe operation as originally intended, engineered, or designed. All work and services provided under this recommendation shall be performed in strict compliance with all applicable rules, regulations, codes, laws, and manufacturer's recommendations and/or requirements.

888 Main Street, Anytown, NJ

Inspection and Site Details



10. Orientation of Front Entrance

• For the purpose of this report, the FRONT entrance of the house is considered to be facing EAST.

11. Occupancy

• Occupied and moderately furnished with moderate amount of household items, personal possessions and stored items.

12. Bedroom Designation and Location

- Master Bedroom #1: Upper level at West side overlooking patio deck
- Bedroom #2: Upper level at East side looking toward front of house
- Bedroom #3: Upper level above Garage

13. Bathroom Designation and Location

- Master Bathroom #1: Connected to Master Bedroom #1
- Bathroom #2: Upper level next to Bedroom #2
- Bathroom #3: Lower level (No bath or shower)

14. Other Rooms or Areas

- Entrance Foyer
- Kitchen
- Dinette (used by current Occupant as Home Office area)
- Living Room
- Laundry Alcove
- Hallways
- Unfinished Basement
- Garage
- Exterior Meter Closet for Electric, Telephone and Gas Utilities

15. Additional Services

Selected Tests:

- Radon Measurement and Laboratory Analysis
- Termite and Other Wood Destroying Insects Inspection with Certification
- Mold Sample Collection and Laboratory Analysis using Surface Swab

888 Main Street, Anytown, NJ

Room/Area ID Photos

1. Room/Area ID Photos

Not Repair Presnt Replac

Not Inspect

Inspect



Master Bedroom #1

Bedroom #2



Bedroom #3

Kitchen

Stanley E. Chow

888 Main Street, Anytown, NJ



Dinette (currently used as Home Office)





Master Bathroom #1



Bathroom #2



Basement



Exterior of House and Adjacent Areas

This section reports on the condition of the exterior building skin and trim. Inspectors are required to inspect the exterior walls, flashing, trim, exterior doors, the stoops, steps, porches and their associated railings, any attached decks and balconies and eaves, soffits and fascias accessible from ground level. Inspectors also inspect entrance walkways, sidewalks, patios, and driveways; vegetation, grading, surface drainage, and retaining walls that are likely to adversely affect the building.

1. Vegetation Affecting Structure



Replac Description:

Trees are in contact with the house

 Trees with overhanging branches extend across roof and gutters of house Observations:

• Trees too close to the building can cause harm through root damage to the foundation. branches abrading the roof and siding, and leaves clogging gutters and providing a path for moisture and insects into the home.

HIGHLY RECOMMEND having all trees trimmed and pruned away from house.



Tree in contact with roof



Tree in contact with roof cause damage to shingles

2. Grading and Surface Drainage



Replac Description:

• Surrounding ground is minimally graded away from house at most areas.

Observations:

Low and settled grading along plant bed at front side of house. RECOMMEND backfill

to regrade away from house.

3. Window Wells



Materials:

Corrugated galvanized steel

 Clear plastic covers at front window wells Observations:

- Window wells are in functional condition with normal wear and tear.
- Keep leaves and debris clear from window wells to allow for proper drainage.

888 Main Street, Anytown, NJ



Re-finish and re-paint front soffit

Observed rotted wood in band trim on South side above stucco.

888 Main Street, Anytown, NJ





Non-functional window hardware

Window cannot be opened

888 Main Street, Anytown, NJ

Parane first stars
Damaged insect screen Damaged window frame 10. Window/Door Frames and Trim Damaged window frame
10. Window/Door Frames and Trim Inspect Inspect Presht Replac V Wood Observations: • Frames and trim are in functional condition.
11. Exterior Caulking
 Inspect Inspect Present Replace The purpose of exterior caulking is to minimize air flow and moisture through cracks, seams, and utility penetrations/openings. Controlling air infiltration is one of the most cost effective energy-efficient measures in modern construction practices. A home that is not sealed will be uncomfortable due to drafts and will use about 30% more energy than a relatively air-tight home. In addition, good caulking and sealing will reduce dust and dirt in the home and is one of the simplest energy efficient measures to install. Observations: Caulking and sealants are in good functional condition with no major visible damage or material defects.
12. Garage Entrance Door
Not Inspect Not Present Repair Replac Material: X Image Image Present Observations: Observations: Image Image Image Image Image Image Image
13. Garage Door(s)
 Inspect Inspect Presht Repair Repair Not Repair Repair One 7'x16' fiberglass sectional roll-up door Observations: Overhead garage door is in good functional condition with no major visible damage or material defects.
14. Garage Door Openers
Inspect Not Presnt Repair Replac Description: X SEARS CRAFTSMAN • 1/2 Horsepower
Stanley E. Chow Page 13 of 42 PRIME Building Inspectio

888 Main Street, Anytown, NJ



Roofing

This section reports on the roof coverings and the method used to inspect the roof. Inspectors examine the roof covering, roof drainage systems, flashings, skylights, chimneys and roof penetrations.

1. Roof Style and Pitch	1.	Roof	Style	and	Pitch
-------------------------	----	------	-------	-----	-------

• Multi-Gable roof

2. Method of Roof Inspection

- Walked on roof surface
- Visual examination from Bedroom window due to excessive landscaping and other physical obstructions restricting ladder access.

3. Roof Covering



Description:

- Standard asphalt composition shingles
- Age: • Over 20 years
- Observations:
- Roof shingles appear to be in the last third of their life cycle.
- Roof covering is in poor condition and is near the end of its useful service life.
- RECOMMEND replacement with three years.

• Algae stains on roof shingles indicate a high moisture level in shingles. HIGHLY RECOMMEND engaging a qualified roofing contractor for further review and evaluation; and to repair and/or replace roof shingles as necessary.



Algae growth on roof

4. Flashings



Materials: • Metal Observations:

• Flashings not inspected due to concealment by roof covering and wall siding.



Page 15 of 42 PRIME Building Inspections



Add downspout extension

Missing downspout section

888 Main Street, Anytown, NJ



Add downspout extension

Leaves and debris in gutters

Structure

This section describes the foundation, floor, wall, ceiling and roof structures and the method used to inspect any accessible under-floor crawl space areas. Inspectors inspect and probe the visible structural components of the home, including the foundation and framing, where deterioration is suspected or where clear indications of possible deterioration exist. Probing is not done when doing so will damage finished surfaces or when no deterioration is visible or presumed to exist. Inspectors are not expected to offer an opinion as to the structural adequacy of any structural systems or components or provide architectural services or an engineering or structural analysis of any kind. Despite all efforts, it is impossible for a home inspection to provide any warranty or guarantee that the foundation, and the overall structure and structural elements of the building are adequate and sound. PRIME Building Inspections recommends that if the client is at all uncomfortable with this condition or our observations, a qualified licensed structural engineer be consulted to independently evaluate any specific concern or condition prior to making a final purchase decision.

1. Foundation Type

• Fully excavated deep foundation with continuous masonry walls and concrete floor slab (basement).

2. Foundation Walls



Cast-in-place concrete

Observations:

• Foundation walls are in good functional condition with no major visible damage or material defects.

• Observed crack beneath basement stair next to security alarm panel. Crack was less than 1/8" in width at the widest gap. No indications of past or active water intrusion were observed. RECOMMEND monitoring for water intrusion and movement. Contact qualified licensed structural engineer for review and evaluation if future water intrusion and/or movement is evident.



Minor wall crack in foundation wall

3. Foundation Floor



• Concrete slab Observations:

• Foundation floor is in good functional condition with no major visible damage or material defects.

```
Stanley E. Chow
```

Page 18 of 42

PRIME Building Inspections

888 Main Street, Anytown, NJ



8. Limitations of Structure Inspection

• Full inspection of all structural components (posts/girders, foundation walls, sub flooring, and/or framing) is not possible in areas/rooms where there are finished walls, ceilings and floors.

• Engineering or architectural services such as calculation of structural capacities, adequacy, or integrity are not part of a home inspection.

Stanley E. Chow

Page 19 of 42

PRIME Building Inspections

Interior

This section reports on the Interior portion of the home. Inspectors inspect walls, ceilings, floors, steps, stairways and railings, installed countertops and a representative number of installed cabinets, and representative number of doors and windows. Garage doors and automatic garage door operators are inspected for proper function and the operation of installed safety features. If the home is occupied, the furniture and possessions of the current occupant often conceal some areas/items. These areas are exempt from inspection. Reasonable attempts are made to more closely inspect behind the furniture and possessions if any hint of a problem is found or suspected.

1. Walls and Ceilings

<i>JS</i>
 Materials: Painted drywall Observations: Walls and ceilings are in functional condition with normal wear and tear. Observed indications of ceiling repairs at Master Bedroom #1 and Bedroom #3. Moisture content at Master Bedroom #1 measured 1.7% to 3.2%. Bedroom #3 measured 7.4% to 8.1% next to skylight. No active water leaks or high moisture levels was observed.
 Materials: Carpet throughout except where noted. Ceramic tile in Kitchen and Bathrooms Concrete in Garage Observations: Floors are in functional condition with normal wear and tear, except where noted below. Minor floor squeaks in upper level Hallway.
Description: • Hollow core wood doors Observations: • Interior doors are in functional condition with normal wear and tear.
Observations: • Closets are in functional condition with normal wear and tear. • Finished storage area concealed behind closet in Bedroom #2.
<i>ąs</i>
 Observations: Stairs and railings are in functional condition with normal wear and tear. FYI: Handicap stair lift was not inspected or tested; and is not within the scope of this home inspection. SAFETY CONCERN: The opening between balusters (vertical posts comprising barrier in railings) is 6 inches. A toddler can very easily fall through this spacing from the landing to floor below. Although 6" spacing was adequate when home was built current building safety standards now allow a maximum of 4" between balusters. Consider installing appropriate safety guards as necessary.

888 Main Street, Anytown, NJ



Stanley E. Chow

Page 21 of 42 PRIME Building Inspections



Seal openings in fire separation wall and ceiling

10. Limitations of Interiors Inspection

• There were a moderate amount of personal/household items in each room. Furniture, storage, appliances and/or wall hangings are not moved to permit inspection and may block defects.

• RECOMMEND a thorough review of interior areas during final walk-through inspection prior to closing.

Bathrooms

Bathrooms can consist of many features from whirlpool tubs and showers to toilets and bidets. Because of all the plumbing involved it is included here as a separate area. Fixtures and faucets, functional water flow, leaks, and cross connections are inspected. Moisture, water leaks, failed caulk and tile grout can cause mold, mildew and other problems that may be undetectable within the walls or under flooring. It is important to routinely maintain all bathroom caulking and tile grout, because minor imperfections will result in water migration and damage behind finished surfaces.

1. Bathtubs



• Whirlpool tub in Master Bathroom

- Observations:
- Water supply to tub and showerhead were test-operated and functioned normal.
- Whirlpool function was not tested due to obstruction in whirlpool tub.



Whirlpool function was not tested due to obstruction in whirlpool tub.

2. Showers



• Surround in Bathroom #2 is ceramic tile

Observations:

• Showerhead is loose and not secured to wall. RECOMMEND repair to prevent water intrusion to inside of wall and to prevent damage to pipes.

888 Main Street, Anytown, NJ



Showerhead not secured to wall

3. Toilet(s)



Obervations:

- Toilets were test-operated and functioned normal.
- Toilets are in good functional condition with no major visible damage or material defects.

4. Exhaust Fans Not Inspect

Inspect

Not Presnt

Repair Replac Observations:

• Exhaust fan at Bathroom #3 is not functional. RECOMMEND replacement by a qualified and licensed electrical contractor.

5. A Word About Caulking and Bathrooms

Х

• Caulking at all bathrooms are in good functional condition with no major visible damage or material defects.

• Water intrusion from bathtubs and shower enclosures is a common cause of damage behind walls, sub floors, and ceilings below bathrooms. Annual re-caulking and grouting of tub and shower areas is a preventive maintenance task.

Appliances

The Inspector observed and test-operated the basic functions of the following appliances: permanently installed dishwasher through its normal cycle; stove, permanently installed ovens, trash compactor, in-sink garbage disposal unit, ventilation equipment or range hood, permanently installed microwave oven, and washer/dryer laundry appliances. Interior refrigerator/freezer temperatures are not tested. Inspection of stand-alone freezers and secondary refrigerators are not inspected. No opinion is offered as to the adequacy of dishwasher operation. Oven self or continuous cleaning operations, cooking functions, clocks, timing devices, lights and thermostat accuracy are not tested as part of this inspection. Appliances are not moved and the condition of any walls or flooring hidden by them cannot be inspected and reported upon.

1. Stove and Ovens
 Inspect Inspect Presh Repair Description: General Electric Profile Natural Gas Observations: Test-operated and functioned normal. Stove and oven are in good functional condition with no major visible damage or material defects, except as noted below. Right rear burner requires minor adjustment to increase BTUH output matching other burners.
2. Kitchen Exhaust Fan and Hood
Not Replac Description: X General Electric • Recirculating type. No exterior exhaust.
3. Microwave
Inspect Not Presh Repair X Description: • GE Profile Observations: • Test-operated and functioned normal. • No microwave leakage.
4. Dishwasher
Inspect Inspect Presit Replac X D D D Servations: • Not tested. Dishes in machine.
Disburgebar filled with disbar
Dishwasher filled with dishes

Stanley E. Chow

Page 25 of 42

PRIME Building Inspections

888 Main Street, Anytown, NJ



Stanley E. Chow



Inspect	Inspect	Presnt	Replac	0
				•
<u> </u>				da

Observations:

• Rigid corrugated dryer vent is in good functional condition with no major visible damage or material defects.

Overhead HVAC obstruction

Attic and Insulation

This section reports on the method used to inspect any accessible attics; and describes the insulation and vapor retarders used in unfinished spaces when readily accessible and the absence of insulation in unfinished spaces at conditioned surfaces. Inspectors inspect insulation and vapor retarders in unfinished spaces when accessible and passive/mechanical ventilation of attic areas, where present.

20"x23" attic scuttle located in Closet at Master Bedroom #1

1. Attic Access





Limited attic access in closet



Limited attic access with overhead obstruction

2. Method of Attic Inspection

• Viewed from scuttle opening due to limited access and obstruction.

3. Insulation in Unfinished Spaces



Description: • Fiberglass batt insulation

Depth/R-Value: 6" R-19 where visible.

Observations:

• IMPROVE: Insulation level in the attic is typical for homes this age. RECOMMEND additional insulation to meet current standards.



Stanley E. Chow

Page 29 of 42PRIME Building Inspections

Heating and Air Conditioning

This section reports on the energy source and the distinguishing characteristics of the heating, ventilation and air-conditioning systems (often referred to as the HVAC system). This system is the climate control system for the structure. The goal of this system is to keep the occupants at comfortable levels with healthy indoor air quality and adequate ventilation rates while keeping energy and maintenance costs at a minimum. Inspectors examine readily openable access panels and visually inspect the installed heating equipment and associated vent systems, flues and chimneys; and central air conditioning equipment and distribution systems. The HVAC system inspection is general and not technically exhaustive. The inspector will test the heating and air conditioner using the thermostat and/or other normal controls. PRIME Building Inspections recommends that a standard, seasonal or yearly, Service and Maintenance Contract with an experienced and qualified HVAC contractor be obtained. This provides a more thorough investigation of the home's heating, air conditioning and filtering system as well as maintaining it at peak efficiency and extending equipment service life.

- ,	
1. Thermostat(s)	
Not Presnt Repair X	 Description: Digital programmable thermostat for heating and cooling. Located on wall in lower level Hallway next to stair Observations:
	Thermostat test-operated and functioned normal.
2. Heating System	
Inspect Inspect Presnt Repair	 Natural gas forced hot air furnace and air handler Location: Basement Manufacturer: CARRIER Weathermaker 8000 Model No. 58TUA100-10116 Serial No. 4195A11547 Age and Capacity: Manufacture date: 1995 Capacity: approximately 100,000 BTUH capacity Observations: Heating system is in functional condition with normal wear and tear. RECOMMEND further evaluation and complete HVAC system tune-up by a qualified
2 Eporal Source	licensed HVAC contractor.
3. Energy Source Not Not Presnt Repair Repair	
X	 For Heating: Natural Gas Gas meter located in exterior Meter Closet next to driveway Observations: No deficiencies noted.
4. Safety Switch	
Inspect Inspect Presnt Repair X	Observations: • No deficiencies noted.
5. Combustion Air	
Inspect Inspect Presnt Repair X	Observations: • No deficiencies noted.

Stanley E. Chow

6. Venting, Flue(s), and Chimney(s)



• Metal vent pipe Observations:

• Observed combined furnace/water heater vent pipe is too close to combustibles and does not meet current safety and fire prevention standards. HIGHLY RECOMMEND further review and evaluation by a qualified licensed HVAC contractor and to remediate deficiencies and defects to minimize fire risk.

• Observed transition connector pipe combining furnace and water heater vents are potentially undersized for safe exhaust of flue gases and efficient operation of appliances. HIGHLY RECOMMEND further review and evaluation by a qualified licensed HVAC contractor and to repair and remediate deficiencies and defects.



Vent pipe too close to combustibles

Review vent pipe sizes

7. Cooling System

Inspect	Not Inspect	Not Presnt	Repair Replac	D
X				•
^				

Description:

- Central AC Compressor/Condenser unit
- Location: Exterior on South side
- Manufacturer: LENNOX
- Model No. HS18-461-4P
- Serial No. 5784E39481
- Age and Capacity:
- Approximately 24 years (manufactured 05/87)
- Cooling Capacity: approximately 2 1/2 tons
- Observations:

• Cooling system is in functional condition with normal wear and tear, except as noted below.

- The insulation is weather-worn at exterior refrigerant line. RECOMMEND replacement of insulation for increased efficiency and energy-savings.
- Observed debris inside unit Compressor/Condensing unit. RECOMMEND removing debris and cleaning unit for proper function and increased efficiency.

• RECOMMEND further evaluation and complete HVAC system tune-up by a qualified licensed HVAC contractor.

888 Main Street, Anytown, NJ

John and Jane Doe



Stanley E. Chow

Page 32 of 42 PRIME Building Inspections

888 Main Street, Anytown, NJ

12. Wood-burning Fireplace/Heater



- Replac Description:
 - Prefabricated wood-burning fireplace with metal chimney flue
 - Located in Living Room
 - Observations:
 - Fireplace is in functional condition with normal wear and tear.
 - Manual damper was test-operated and functioned normal.
 - Leftover ashes found in fireplace.
 - RECOMMEND engaging a qualified and experienced chimney sweep to inspect and clean chimney flue for safe and efficient operation.





Fireplace chimney cap

Fireplace

13. Other Components



Description: • Humidifier Observation:

• Indications of past water leak from Humidifer observed on furnace duct. RECOMMEND removal of humidifier by a qualified licensed HVAC contractor to mitigate water leaks and prevent potential growth of mold.



Plumbing

This section reports on the Plumbing system and describes the water supply, drain, waste and vent piping materials and the water heating equipment, energy source and location of the main water and main fuel shut-off valves, when readily viewable or known. Inspectors examine the interior water supply and distribution systems, fixtures and faucets, the drain waste and vent systems (including fixtures for conveying waste), the water heating equipment (vent systems, flues and chimneys of water heaters or boiler equipment), fuel storage and distributions systems for water heaters and/or boiler equipment and drainage sumps, sump pumps and associated piping. Some simple plumbing repairs, such as a typical trap replacement, can be performed by a competent handyman. However, any more complex issues such as incorrect venting or improperly sloped drains should be repaired by a qualified licensed plumbing contractor. All gas-related repairs should only be performed by a qualified licensed plumbing contractor.

1. Water Supply Source

• Public municipal water supply



888 Main Street, Anytown, NJ



Stanley E. Chow

Page 35 of 42 PRIME Building Inspections

888 Main Street, Anytown, NJ



888 Main Street, Anytown, NJ



Sump basin

Stanley E. Chow

Page 37 of 42PRIME Building Inspections

Electrical

This section reports on the electrical system and describes the amperage and voltage rating of the electric service, the location of the main disconnect and any sub panels, the presence of solid conductor aluminum branch circuit wiring, the presence or absence of smoke detectors and wiring methods. Inspectors are required to inspect the visible portions of the overhead service drop from the utility to the house, the service entrance conductors, cables and raceways, the service equipment and main disconnects, the service grounding, the interior components of the service panels and sub panels, the conductors, the over-current protection devices (fuses or breakers), ground fault circuit interrupters and a representative number of installed lighting fixtures, switches and receptacle outlets. All issues or concerns listed in this Electrical section should be construed as current and a potential personal safety or fire hazard. Recommendation for repairs should be considered a priority and should only be made by a qualified licensed electrician.





2. Service Entrance Wires



- 3. Electrical Service Rating
 - 150 amps

4. Main Service Panel(s)



• Manufacturer: SIEMANS

Observations:

• Main panel is in functional condition with normal wear and tear, except as noted below.

• Observed 3 screws were missing at dead front cover where 6 screws are required. One of the 3 installed screws was pointed and wrong size. Blunt-tip screws are required at electric panels to prevent accidental piercing of wires and cables. HIGHLY RECOMMEND engaging a qualified licensed electrical contractor to install proper screws.



Main electric panel in Garage



Main electric panel

Stanley E. Chow

Page 38 of 42 PRIME Building Inspections

888 Main Street, Anytown, NJ



Dointed scrow found at doad front cover



۰f alactric nnin

Pointed screw fou	und at dead front cover	Interior of main electric panel		
5. Service Grounding				
	cription: side the residence			
6. Distribution Wiring				
X Obse	cription: iring type: non-metallic sheathed cable "F ervations: stribution wiring in good functional condi erial defects.			
7. Overcurrent Protectio	n			
Obset • Ov	e: cuit Breakers ervations: rercurrent protection is in functional conc erial defects.	dition with no major visible damage or		
8. Wall and Light Switch	es			
X Gr	cription: ounded ervations: all and light switches are in good function naterial defects.	nal condition with no major visible damage		
9. Receptacle Outlets				
• Re • SA pin s		lets in Bedroom #2 were painted. Ground ed plug insertions. HIGHLY RECOMMEND		

Stanley E. Chow

Page 39 of 42 **PRIME Building Inspections**



Outlet in Bedroom #2 blocked by paint





END OF REPORT

Thank you for selecting PRIME Building Inspections for your home inspection and testing services. It has been our pleasure to serve you.

If you have any questions about this Home Inspection Report, please feel free to contact us at Toll-Free: 888.920.0500 or via email at Inspector@PrimeBuildingInspections.com. We will gladly clarify and interpret any parts of this Report to provide you with a better understanding the inspection and our observations.

If you have any future need for home inspections or testing, please call us Toll-Free: 888.920.0500 and we will offer you a \$50 discount off our standard fee. Please mention the Inspection Number at the front of this Report when scheduling the inspection.

If you have any family and friends that require home inspection services or testing, please ask them to call us Toll-Free: 888.920.0500 and we will also offer them a \$50 discount off our standard fee. We will also send you a special gift to "thank you" for referring us. Please mention the Inspection Number at the front of this report when scheduling the inspection.

Please visit our website at www.PrimeBuildingInspections.com to learn more about our services.

Best Wishes and Good Luck,

Stanley E. Chow, Chief Inspector and Principal PRIME Building Inspections

Copyright 2011-2012 PRIME Building Inspections. All Rights Reserved.